



John G. Degenkolb

FIRE PROTECTION ENGINEER • CODE CONSULTANT

1720 Chevy Knoll Dr., Glendale, California 91206

Telephone: (213) 245-3075

March 3, 1973

Duane Pearsall
STATITROL INC.
140 S. Union
Lakewood, Co. 80228

S T A T E M E N T

Consulting Services as per statement of Feb. 5, 1973 \$284.65

Duane:

The Southern Standard Building Code Congress is having a special hearing on Feb. 27-28 in Florida concerning the proposed adoption of the High Rise code changes I submitted. They have asked that I be there.

If you will review the ICBO high rise proposal, you will note that they have provisions for detectors in Mechanical Equipment Rooms, in the return air portion of the duct system to the extent that a detector is required at the opening into the vertical shaft. I am not satisfied with it as it is written. Do you have any suggestions? Remember, the detectors are not being provided as an early warning system but simply to stop the re-circulation of smoke. There are also to be provisions re-instituted for the detector in the elevator lobby. I have just learned that they deleted that requirement which they put in the year before.

If it is alright with you, I will be attending and be billing you for about 1/4 of the costs. If not, let me know.

John G. Degenkolb
John G. Degenkolb